

CONTACT DETAILS

Flordeck	Van 1
17 Murray Road	
Rochester	
Kent	ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID	FLVAN1-001	Description	Hilti DC-SE20
Class	2	Voltage	110 V
Serial No.	23780304		
Test Date	05/01/2017	Test Time	10:38:28

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current A	Ω Ω Ω	
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.00 KVA	Pass
LEAKAGE:		mA	Pass
FLASH TEST	Test Voltage kV	mA	
	kV	mA	
	kV	mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC	Tester Name	Tim Munday
17 Murray Road	Qualifications	
Rochester	Position	
Kent	Signature	
ME2 4HJ		

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-002 Description COLLOMIX
 Class 2 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 10:48:33

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current A	Ω Ω Ω	
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.00 KVA	Pass
LEAKAGE:		mA	Pass
FLASH TEST	Test Voltage kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-003 Description BOSCH GWS22-230H
 Class 2 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 10:55:12

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current A	Ω Ω Ω	
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.00 KVA	Pass
LEAKAGE:		mA	Pass
FLASH TEST	Test Voltage kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-004 Description BOSCH GWS22-230H
 Class 2 Voltage 110 V Serial No. 502 000033
 Test Date 05/01/2017 Test Time 11:27:21

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current A	Ω Ω Ω	
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.00 KVA	Pass
LEAKAGE:		mA	Pass
FLASH TEST	Test Voltage kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-005 Description BOSCH GAS50
 Class 1 Voltage 110 V Serial No. 0 601 989 141
 Test Date 05/01/2017 Test Time 11:23:02

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current 25 A	0.15 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.00 KVA	Pass
LEAKAGE:		<0.10 mA	Pass
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-006 Description BOSCH GAS50
 Class 1 Voltage 110 V Serial No. 112000010
 Test Date 05/01/2017 Test Time 11:33:26

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current 25 A	0.15 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		1.34 KVA	Pass
LEAKAGE:		<0.10 mA	Pass
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-007 Description BOSCH GWS850C
 Class 2 Voltage 110 V Serial No. 402000013
 Test Date 05/01/2017 Test Time 11:39:29

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current A	Ω Ω Ω	
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.46 KVA	Pass
LEAKAGE:		mA	Pass
FLASH TEST	Test Voltage kV	mA	
	kV	mA	
	kV	mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-008 Description BOSCH GBH2-20SRE
 Class 2 Voltage 110 V Serial No. 38300138
 Test Date 05/01/2017 Test Time 11:47:22

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current A	Ω Ω Ω	
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.31 KVA	Pass
LEAKAGE:		mA	Pass
FLASH TEST	Test Voltage kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-009 Description DAINES MIXER
 Class 1 Voltage 110 V Serial No. 1873
 Test Date 05/01/2017 Test Time 11:54:11

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current 25 A	0.07 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.76 KVA	Pass
LEAKAGE:		<0.10 mA	Pass
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-010 Description 110V 16A EL
 Class 1 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 12:24:44

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 25 A	0.19 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-011 Description 110V 16A EL
 Class 1 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 12:32:27

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 25 A	0.18 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck	Van 1
17 Murray Road	
Rochester	
Kent	ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID	FLVAN1-012	Description	110V 16A EL
Class	1	Voltage	110 V
Serial No.	N/A		
Test Date	05/01/2017	Test Time	12:40:27

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 25 A	0.18 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC	Tester Name	Tim Munday
17 Murray Road	Qualifications	
Rochester	Position	
Kent	Signature	
ME2 4HJ		

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-013 Description 110V 16A EL
 Class 1 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 12:45:48

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 25 A	0.19 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-014 Description 110V 16A EL
 Class 1 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 12:50:34

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 25 A	0.19 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-015 Description 110V 16A EL
 Class 1 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 12:53:36

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 25 A	0.18 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-016 Description 110V 16-32A CONVERT
 Class 1 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 12:57:35

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 10 A	<0.01 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV	mA	
	kV	mA	
	kV	mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-017 Description 110V 16-32A CONVERT
 Class 1 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 12:59:50

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 25 A	0.03 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID FLVAN1-018 Description 110V 32-16A CONVERT
 Class 1 Voltage 110 V Serial No. N/A
 Test Date 05/01/2017 Test Time 13:02:23

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 25 A	0.02 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name Tim Munday
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID **FLVAN1-019** Description **110V 32-16A CONVERT**
 Class **1** Voltage **110 V** Serial No. **N/A**
 Test Date **05/01/2017** Test Time **13:03:49**

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			Pass
EARTH CONTINUITY:	Test Current 25 A	0.02 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		KVA	
LEAKAGE:		mA	
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name **Tim Munday**
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID **FLVAN1-020** Description **5KVA 110V TRANSFORMER**
 Class **1** Voltage **230 V** Serial No. **N/A**
 Test Date **05/01/2017** Test Time **13:13:31**

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current 10 A	0.07 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.14 KVA	Pass
LEAKAGE:		<0.10 mA	Pass
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name **Tim Munday**
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID **FLVAN1-021** Description **5KVA 110V TRANSFORMER**
 Class **1** Voltage **230 V** Serial No. **N/A**
 Test Date **05/01/2017** Test Time **13:15:30**

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current 10 A	0.09 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.13 KVA	Pass
LEAKAGE:		<0.10 mA	Pass
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name **Tim Munday**
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID **FLVAN1-022** Description **3KVA 110V TRANSFORMER**
 Class **1** Voltage **230 V** Serial No. **N/A**
 Test Date **05/01/2017** Test Time **13:20:00**

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current 10 A	0.04 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.18 KVA	Pass
LEAKAGE:		<0.10 mA	Pass
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name **Tim Munday**
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ

CONTACT DETAILS

Flordeck Van 1
 17 Murray Road

 Rochester
 Kent ME2 4HJ

APPLIANCE DETAILS AND TEST RESULTS

Appliance ID **FLVAN1-023** Description **3KVA 110V TRANSFORMER**
 Class **1** Voltage **230 V** Serial No. **N/A**
 Test Date **05/01/2017** Test Time **13:22:18**

Notes

TEST TYPE	PARAMETERS / PASSBANDS	RESULT	STATUS
VISUAL INSPECTION			Pass
REMOVABLE CORD TEST			
EARTH CONTINUITY:	Test Current 10 A	0.04 Ω Ω Ω	Pass
INSULATION RESISTANCE:		>99.90 MEG Ω MEG Ω MEG Ω	Pass
LOAD:		0.18 KVA	Pass
LEAKAGE:		<0.10 mA	Pass
FLASH TEST	Test Voltage kV kV kV	mA mA mA	
REPAIR CODE: 0		OVERALL STATUS:	Pass

CONTRACTOR DETAILS

FLORELEC Tester Name **Tim Munday**
 17 Murray Road Qualifications
 Rochester Position
 Kent Signature
ME2 4HJ